

# SERVICE BULLETIN



No. : 0IVL20050038

Date : 2005-11-24

Model	Factory	Factory Model	Suffix	Model No.	Factory	Factory Model	Suffix	Model No.
	EKHQ	42LP1D-UA	ALUSLL	42LP1D-UA	ENMX	42LP1D-UA	ALUSLL	42LP1D
Buyer	Buyer Name	Buyer Code	Buyer Name	Buyer Code	Buyer Name	Buyer Code		
	LGEUS	US000001	LGEAI	US000002				
EFFECTIVE DATE	2005-11-23		EFFECTIVE FROM(SERIAL NO.)				N/A	
Subject	No Video 42LP1D-UA.							
No.	Loc No.	Before Change		After Change		Note	K-Code	Remark
		Part No	DESC./SPEC.	Part No	DESC./SPEC.			
<b>Reason Of Change</b>								
<p>1. Symptom: Sound but no video. The failures that are visualized are normally black. In detail, the operations of audio and front index are normal. (If you press any button, front index display and audio states are changed.)</p> <p>2. Corrective Action: For the case of A-1 items, change the T-con board of LCD module to the latest version. * If T-CON board is not available, then change the LCD module.</p>								
<a href="#">42LP1D_NoVideo.pdf</a>								

\*\* FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

NOTE(**) : INTERCHANGEABILITY CODE				KEY-WORD CODE
	Parts	Set		
A	Original	Early	Original or new parts may be used in early or late production sets. Use original parts until exhausted, then stock new parts.	1. To improve performance 2. To improve productivity
	New	Late		
B	Original	Early	Original parts may be used in early production sets only. New parts may be used in early or late production sets. Use original parts where possible, then stock new parts.	3. To improve reliability 4. Change of material or dimension
	New	Late		
C	Original	Early	New parts only may be used in early or late production sets. Stock new parts.	5. Addition 6. Deletion
	New	Late		
D	Original	Early	Original parts only may be used in early production sets. New parts may be used in late production sets only. Stock original and new parts.	7. Correction
	New	Late		

CHIEF ENGINEER , *approved*  
Factory.